

TECHNICAL NOTE TN.JS-002

Approval number: Design: D667 Manufacturing: M667, Maintenance: AMO1179

# **Technical Note TN.JS-002**

## 22 July 2011

TITLE Lift Bush Re-instalment

### DESCRIPTION

The Lift Bushes (Part No 1A-1.06.20) are designed to be removable and as such are bonded with Loctite into the Lift Pipes (Part No 1A-1.06.10). Due to machining tolerances it is not uncommon for the bushes to come out during wing de-rigging.

### **INSTRUCTIONS**

- 1. Removal of bushes:
  - a. Heat the bush carefully to approx. 150 °C to release the Loctite using a miniature mobile soldering iron (or small gas flame).
  - b. Heat need only be applied briefly otherwise the surrounding composite may be damaged.
  - c. Knock the bush out from the opposite side, using a long solid bar.
- 2. Bonding of lift bushes
  - a. Clean the area where the bush seats with a miniature grinding tool. Ensure there are no obstructions between the bush and the carry pipe,
  - b. Inspect inside the Carry Pipe and thoroughly clean and dry the inside surface
  - c. Assembly the glider to ensure the bush seats fully.
  - d. Disassemble glider
  - e. Apply Loctite 243 Medium Strength onto the bush surfaces and press bushes back into the carry pipes
  - f. Assemble glider immediately, and follow Loctite curing time of approximately 8hrs
  - g. Inject 5ml of linseed (flax seed) oil into the carry pipe through the bush
  - h. Using a pipe cleaner ensure the linseed oil is evenly spread over the entire inner surface

Document name:	Document number:	Rev:	Document issue date:	
Lift Bushes	TN.JS-002	03	22 July 2011	Page 1 of 2



TECHNICAL NOTE TN.JS-002

Approval number: Design: D667 Manufacturing: M667, Maintenance: AMO1179

#### MATERIAL

No material is supplied

Additional material required;

- 1. Loctite 243 Medium Strength
- 2. Linseed (flax seed) oil
- 3. Pipe cleaner or clothe to spread the linseed oil inside the carry pipe

#### MASS AND BALANCE

No change to mass and balance.

#### MANUALS

No change to Flight Manual. Changes to Maintenance Manual can be expected and will be addressed through a Service Bulletin to be issued in due course.

#### NOTES

If the gel coat around lift bushes is damaged perform repairs as per JS Repair Manual.

ocument issue date:
22 July 2011 Page 2 of 2
D